



Phillips 66® API FA-4 Products Limited Warranty

Phillips 66 Commercial Lubricants Division guarantees that its Phillips 66 Guardol® FE 10W-30 meets or exceeds the specifications stated by Phillips 66, and that it is free from defects. Therefore, Phillips 66 will pay for parts and labor deemed reasonably necessary to repair damage to engines or other pieces of equipment if it can be demonstrated that the damage was caused solely and directly by a breach of this warranty by Phillips 66.

This warranty protects the following equipment against lubricant-related failure in on-highway service:

- 2010 and newer Detroit Diesel (DTNA) engines
- 2014 and newer Cummins, International / Navistar, PACCAR and Volvo / Mack engines

This warranty protects your equipment against lubricant-related failure as long as:

- It is serviced with Phillips 66 Guardol FE 10W-30 (API FA-4) and the equipment is used under normal operating conditions in over-the-road service
- The engine or equipment was operated as specified by the engine or equipment manufacturer's maintenance schedule
- The lubricant was changed as specified by the engine or equipment manufacturer maintenance schedule

- Written documentation or maintenance records are provided that show the engine or equipment was serviced and maintained at regular intervals as specified by the manufacturer
- The proper lubricant level has been maintained in the engine or equipment through documentation of frequency of oil make-up
- A historical record of lubricant brands and types used during the life of the engine or equipment is provided, and the date of last use prior to switching to Phillips 66 Guardol FE 10W-30
- Phillips 66 is provided with a new and used sample of the Phillips 66 Guardol FE 10W-30, with the plant fill codes, that are believed to be the cause of the engine or equipment failure, and Phillips 66 personnel are allowed to inspect the damaged engine or equipment, take samples, and perform lab tests on the samples

- Prompt notice of the problem is given to allow Phillips 66 to investigate the problem
- This warranty shall be void if: (1) the damage is related to use of other competitive lubricants; (2) the damage is related to engine or equipment modification; or (3) the owner/operator has failed to operate or maintain the engine or equipment as required by the manufacturer

PHILLIPS 66 IS NOT RESPONSIBLE FOR (AND HEREBY DISCLAIMS ALL LIABILITY FOR) SPECIAL, INDIRECT, INCIDENTAL OR CONSEQUENTIAL DAMAGES OR LOSSES. THIS WARRANTY IS IN LIEU OF ALL OTHER WARRANTIES REGARDING PHILLIPS 66 BRANDED LUBRICANTS, EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO THOSE OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.

To submit a claim under this warranty, please contact your Marketer Sales Representative, Lube Engineer or call a Hotline Consultant @ 1-877-445-9198 to report the problem so we can resolve it promptly.